

ICS 209 (Oil Spill) - Incident Status Summary										Version Name: Phase II				
Incident Name: Spirit Of Sacramento										Period: Phase II [09/09/2016 09:00 - 09/16/2016 09:00]				
<b>Spill Status (Estimated)</b>										<b>Equipment Resources</b>				
<b>Source Status</b>		<b>Remaining potential</b>		600		<b>Kind</b>		<b>Ordered</b>	<b>Available / Staged</b>	<b>Assigned</b>	<b>Out-Of-Service</b>	<b>Total Count</b>		
SECURED		<b>Rate of spillage</b>		0 \$/hr		Boom		0	0	400	0	400		
		<b>Volumes measured in</b>		gal		Manpower: Responder		0	0	2	0	2		
		<b>Since Last Report</b>		<b>Total</b>		Vessel		0	1	0	0	1		
Total Volume Spilled		0		0										
<b>Mass Balance (Estimated)</b>										<b>Personnel Resources</b>				
<b>Volumes measured in</b>										<b>Organization</b>	<b>People in the Field</b>	<b>People in Cmd. Post</b>	<b>Total People On Scene</b>	
Recovered Product		0		0		Federal		0	21	21				
Evaporation		0		0		State		0	5	5				
Natural Dispersion		0		0		Local		0	3	3				
Chemical Dispersion		0		0		RP		0	0	0				
Burned		0		0		Contract Personnel		2	1	3				
Floating, Contained		0		0		Volunteers		0	0	0				
Floating, Uncontained		0		0		<b>Totals</b>		<b>2</b>	<b>30</b>	<b>32</b>				
Onshore		0		0										
<b>Waste (Estimated)</b>										<b>Special Notes</b>				
<b>Type</b>	<b>Recovered</b>	<b>Stored</b>	<b>Disposed</b>	<b>UOM</b>		<p>On 04SEP16, Sector San Francisco (Sector) was notified that R/V SPIRIT OF SACRAMENTO was taking on water IVO Frank's Tract near Bethel Island, CA. The vessel sank and became submerged upside down with the hull protruding above the surface of the water. The vessel has a total fuel capacity of 4500 gallons and a reported 600 gallons of diesel fuel on board. Only minor sheening was initially reported. The Sector San Francisco Incident Management Division (IMD) was initially unable to contact with owner of the vessel. Due to the proximity of sensitive sites, volume of pollution potential and complexity of the response, the SPIRIT OF SACRAMENTO was determined to be posing a significant threat to the environment. The FOSC authorized access to the Oil Spill Liability Trust Fund (OSLTF) for \$100,000 during phase I, then authorized raising the ceiling \$500,000 in preparation for phase II. An authorization to proceed (ATP) was granted to Global Diving and Salvage, Inc. (Global) for \$80,000; the ATP was raised to \$400,000 on 12 September 16. A safety zone was put into effect seventy five feet from the boom surrounding the vessel or from response equipment, whichever is greater. A Unified Command structure was formed consisting of the USCG, California Department of Fish and Wildlife OSPR (OSPR), and the Contra Costa County Sheriff's Office. IMD was able to contact the owner after determining his physical address and issued a Notice of Federal Interest (NOFI) and Administrative Order for a plan to conduct pollution mitigation operations. The responsible party did not meet the provisions within the Administrative Order, and a Notice of Federal Assumption was delivered at 1200 on 9 September 2016. The current cost as of 14 September 2016 for the project remains at \$36,931.97. Pollution Removal Funding Authorizations have been issued to the Contra Costa County Sheriff's Office for \$70,000 and OSPR for \$150,000. Unified Command is moving forward with pollution removal operations utilizing Global while continuing to work closely with federal, state and local partners to determine the vessel's final disposition. Global reported the vessel had shifted to its starboard side at 0730 on 14 September 2016. Diving operations to prepare the vessel for righting are scheduled to commence 15 September 2016. A minimum of three IMD members will be on scene to monitor operations. A NOAA bathymetry survey is scheduled for 14 September 2016.</p>								
Oil	0	0	0	gal										
Oily Liquid	0	0	0	gal										
Liquid	0	0	0	gal										
Oily Solid	0	0	0	gal										
Solid	0	0	0	gal										
<b>Shoreline Impacts</b>														
<b>Distances measured in</b>														
<b>Degree of Oiling</b>	<b>Affected</b>	<b>Cleaned</b>	<b>Remaining to be Cleaned</b>											
Very Light	0	0	0											
Light	0	0	0											
heavy	0	0	0											
<b>Wildlife Impacts</b>														
					<b>Died In Facility</b>									
<b>Type</b>	<b>Captured</b>	<b>Cleaned</b>	<b>Released</b>	<b>DOA</b>	<b>Euth.</b>	<b>Other</b>								
Bird	0	0	0	0	0	0								
Mammal	0	0	0	0	0	0								
Reptile	0	0	0	0	0	0								
Fish	0	0	0	0	0	0								
Other	0	0	0	0	0	0								
<b>Safety Status</b>														
<b>Type</b>	<b>Amount since last report</b>				<b>Total Amount</b>									
Responder Injury	0				0									
Public Injury	0				0									
Other	0				0									
ICS 209 (Oil Spill) - Incident Status Summary										Last Update By Jake Urrutia At 09/14/2016 13:28 GMT -8:00				
INCIDENT ACTION PLAN SOFTWARE <input type="checkbox"/>		Printed 09/14/2016 13:29 GMT -8:00				Page 1 of 1			©TRG					